DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Brian Spurrier
ADDRESS: _____
APPLICATION DATE _____
DATE EVALUATED: 10/10/07
PROPOSED FACILITY: SFD Mtb
PROPOSED DESIGN FLOW (.1949): 360
PROPERTY SIZE: _____
LOCATION OF SITE: Corner Clear Springs & St Thomas Ct.
PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 5%	0-26	m Sbk C	fr SS Sp	Com Sap few clay	inc.			PS .35 >38"
		26-60	Mass LSap	vfr ns np					
2	Cut Leveled 2-3' deep from original Flat	0-10	Mass Loam Sap	vfr ns np	few scattered @ clay	inc.			PS .35
		10-40	LSap Mass	vfr ns np					
		40-66	LSap Mass	vfr ns np					
3	Flat	0-10	Mass LSap	vfr ns np	weathered Rock				PS .4
		10-60	Mass LSap	vfr ns np					
4	Flat	0-24	Mass LSap	vfr ss np	few clay				PS .4
		24-54	Mass LS Sap	vfr ns np					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	25% Grav.	pump Panel
Site LTAR	.35	.35

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Anthony Coker & Ben Aldridge
OTHER(S) PRESENT: Gary McNeely