13082

4649-97-0660

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ray Blankenship DATE Aug 1, '91 PERMIT NO. 4E3A44

PHONE: Business _____ Home _____

LOCATION 115-2 N. TL 1312 (Flower Home Rd.) TL 1311 (Rankin Hill Rd.) TL into park bear left, ~ 1/4-1/2 mi. on left

SUBDIVISION NAME Palomino Park LOT NO. 44 S. R. No. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 20000 sq ft +/-

Character & Porosity of Soil Sc clay

Percolation Rate 4 4


Topography 4 2%

Depth to Water Table 44

Rock or other impervious formations none obs.

Lot line

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Rankin Septic Tk.

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

PROVEMENTS PERMIT BY AWS Stitt

MMENTS: _____

TIFICATE OF COMPLETION BY _____

STING SYSTEM CHECKED BY: DR Hinson, RS DATE 8-1-91

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

it is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making ovements Permit. DATE _____

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold