13169

IREDELL COUNTY HEALTH DEPARTMENT

Type 4

46A 99 2538

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jeff & Nicki Webster DATE 8/29/91 PERMIT NO. 4E-3-A-43

PHONE: Business _____ Home _____

LOCATION Palomino Park

S. R. No. 1311

SUBDIVISION NAME Palomino Park LOT NO. 43 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area .93

Character & Porosity of Soil clay - s - sp - p

Percolation Rate 4


Topography 2 4%

Depth to Water Table 748"

Rock or other impervious formations non observed

[o] Well

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000/1000 Gals.

Nitrification Field:

No. of Lines 3 @ 100'x3'

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by James Hadler

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Wesley Sparks R.S. DATE 8/29/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

13169

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jeff & Nickie Webster DATE July 26, '91 PERMIT NO. 4E-3A-43

PHONE: Business _____ Home _____

LOCATION I-40 E. TR 1312 (Howe Home Loop) TR 1311 (Rankin Hollow) TL into Coloning Park Loop-left ½ mile on left S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 43 SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

~~Auto. Dishwasher~~ Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 1.23

Character & Porosity of Soil 85 clay


Percolation Rate 14 at 24" near street

Topography 24%

Depth to Water Table 4'+

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000 Gals. 1000 pt.

Nitrification Field:

No. of Lines 2

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed ~~Jeffrey A. Webster~~

IMPROVEMENTS PERMIT BY Jack R. Fincher, RS.

Pump specs: 25 gal/min at Approx. 20' head.

COMMENTS: Follow contour & 24" trench bottom depth. Dist upper line minimum distance 5' off road R/W (85'+). Pressure dosed conventional trench use 1¼" Sch 40 laterals with ONE 5/32" hole every 5' feet. 2' pressure head.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold