IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR GREGORY SHARPE DATE 5/26/88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115 N TL Flowerhouse Loop TL Rankin Hill TL Palamino Park Bear left. Nearend on Left. S. R. No. _____

SUBDIVISION NAME Palamino Park LOT NO. 40 SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Clayey
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	~.35
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	4-8%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'+
			Rock or other impervious formations	none ob.

Lot Area _____

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System NTS.

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 690 Linear Ft. 230
Depth of Stone in Lines 12"

Water Supply: Individual (X)
Public ( )

Installed by Wayne Eller

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY BRH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C. Price DATE 5/26/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

08818

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Gregory & Sharpe DATE May 18, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21 N. TR 1312 (Flower House Lp) TR 1311 (Rankin Hill Rd.) R into park bear left near end on left S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 40 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site ~~Suitable~~	Yes (✓)	No ( )	

Lot Area ~35000 ft²

Character & Porosity of Soil Clay


Percolation Rate 2, 35

Topography 4-8%

Depth to Water Table 41+

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 690 Linear Ft. 230

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: * Renee C. Sharpe

IMPROVEMENTS PERMIT BY [signature], RS.

COMMENTS: Follow contour and install drainfield with 18" cover over stone.

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold