4649-97-2938

15741

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR Gregory D Sharpe DATE 3/11/93 PERMIT NO. 4E3A40

PHONE: Business _____ Home 528-4912

LOCATION Palomino Park

SUBDIVISION NAME Palomino Park S.R. No. _____

LOT NO. 40 SECTION OR BLOCK NO. _____

House ☐ Mobile Home ☑ D/W Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area Existing

Soil Characteristics P


Application Rate P

Topography P

Depth to Water Table 5

Rock or other impervious formations 5

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement ✓ Crawl Space



Plot of System (Not to Scale)

Size of Tank Existing 1000 Gals.

Nitrification Field:

No. of Lines 2(E) 80'x3'

Sq. Ft. 480 Linear Ft. 160

Depth of Stone in Lines 12"

Water Supply: Individual ☑ Public ☐

Installed by F.J Ewen

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY _____

COMMENTS Original S/B bedlayout of level - Speed levelers use to re level all drain lines

CERTIFICATE OF COMPLETION BY Wesley Sparks R.S. DATE 3/11/93

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

15741

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR Gregory D Sharpe DATE 2/4/93 PERMIT NO. 4E 3440

PHONE: Business _____ Home 528-4912

LOCATION Palomino Park, Rankin Hill TL on Palomino straight (R) to 4th lot on (L) from the culdesac.

SUBDIVISION NAME Palomino Park LOT NO. 40 SECTION OR BLOCK NO. _____ S.R. No. _____

House ☐ Mobile Home ☑ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area Existing

Soil Characteristics P


Application Rate P

Topography P

Depth to Water Table B

Rock or other impervious formations S

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement _____ Crawl Space



Plot of System (Not to Scale)

Size of Tank Existing 1000 Gals.

Nitrification Field:

No. of Lines 2 @ 80'x3'

Sq. Ft. 480 Linear Ft. 160

Depth of Stone in Lines 12"

Water Supply: Individual ☑ Public ☐

Installed by _____

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY ROAP Wesley Sparks RS.

COMMENTS (1) Install Dist Box as shown here (2) Install 2 80'x3' lines below original system. Trenches no deeper than 36" to trench bottom.

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS DATE _____

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold