4649 97 5434

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Carol Shumaker DATE 4/15/88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115 - 21 N TL 1312 (Flower House Loop) TL 1311 (Rankin Hill Rd) TL Palamino Park TL 1st St. near end tank S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 26 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil clay
Percolation Rate ~ 3
Topography 6-15%
Depth to Water Table 4'+
Rock or other impervious formations none observed

Lot Area 30000

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by James Huddleston

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: Tank is ~ 40' off M.H.

CERTIFICATE OF COMPLETION BY Andrew C. Queen DATE 4/15/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

08609 10:00

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Carol E. Shumaker DATE April 7 '88 PERMIT NO. ______

PHONE: Business ______ Home ______

LOCATION 115-21 N, To 1312 (Flower House Loop) To 1311 (Rankin Hill Rd.) To Palomino Park To 15th Street near end on Rt. S. R. No. ______

SUBDIVISION NAME Palomino Park LOT NO. 26 SECTION OR BLOCK NO. ______

House ( ) Mobile Home (✓) Business ( ) Other ______

No. Bedrooms 3	No. Bathrooms 2	Character & Porosity of Soil	clay
Garbage Disposal Unit	Yes ( ) No (✓)	Percolation Rate	3
Auto. Dishwasher	Yes (✓) No ( )	Topography	6-15%
Auto. Wash. Machine	Yes (✓) No ( )	Depth to Water Table	4'
Site ~~Suitable~~ PS	Yes (✓) No ( )	Rock or other impervious formations	none obs.

Lot Area 30000 ft² +

___ Basement with Plumbing ___ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by ______

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: X Carol E. Shumaker

IMPROVEMENTS PERMIT BY David L. Hinson, RS.

COMMENTS: follow contour with drainfield, install drainfield at a depth of 30" to bottom of ditch (18" cover). Use drop boxes or flow dividers to distribute effluent.

CERTIFICATE OF COMPLETION BY ______ DATE ______

EXISTING SYSTEM CHECKED BY: ______ DATE ______

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold