4649-97-5650

IREDELL COUNTY HEALTH DEPARTMENT

12263

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Constantina Pappasadokis DATE Dec. 20, '90 PERMIT NO. 4E-3-A27

PHONE: Business _____ Home _____

LOCATION 115-2 N. TL 1312 (Hoover House Loop) TL 1311 (Rowan Kin Hill Rd.)

S. R. No. _____


SUBDIVISION NAME Palomino Park LOT NO. 27 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ PS Yes (✓) No ( )
Lot Area ~30,000 ft²

Character & Porosity of Soil 05 clay
Percolation Rate In. 35
Topography 4-6%
Depth to Water Table 4'+
Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4
Sq. Ft. 1020 Linear Ft. 340
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by James Hudler

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS ~~PERMIT~~ BY _____ DRK

COMMENTS: _____

CERTIFICATE OF COMPLETION BY David R. Hinson, EHS DATE 12-20-90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold