4649-98-2147

IREDELL COUNTY HEALTH DEPARTMENT

13265 (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Alan F Daher DATE 11/26/91 PERMIT NO. 4E-8-A-38

PHONE: Business _____ Home 664-9588

LOCATION _____

_____ S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 38 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 20,000FT²

Character & Porosity of Soil C - (SA - SL)
Percolation Rate .35
Topography 2-9%
Depth to Water Table >48"
Rock or other impervious formations None observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 30 110'x3'
Sq. Ft. 960 Linear Ft. 330'
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by James Hudlow

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Well must be 50' from closest part of septic Tank System. Trailer not on lot at time of completion.

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 7/26/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

12:00

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Alan F Dahar DATE 8/19/91 PERMIT NO. 4E-3-A-38

PHONE: Business _____ Home 664-9588

LOCATION Rankin Hill Rd.

S. R. No. _____

SUBDIVISION NAME Palomino Park LOT NO. 38 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area 20,000 FT²

Character & Porosity of Soil clay (ss - sf)
Percolation Rate .35
Topography 2-10%
Depth to Water Table > 48"
Rock or other impervious formations _____

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3@110' K3'
Sq. Ft. 960 Linear Ft. 330'
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Wesley Sparks R.S.

COMMENTS: Keep all parts of system 50' from the drilled well on lot above this one. Trenches are to start with drop loops on each line. Trenches are to follow slope contour.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold