4649-98-5086

IREDELL COUNTY HEALTH DEPARTMENT

12990

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Christine Beckstead DATE 7/29/91 PERMIT NO. 4E-3-A-31

PHONE: Business _____ Home 663-7262

LOCATION Palomino Park, near section on (R) just before cul de sac

SUBDIVISION NAME Palomino Park S. R. No. 1311

LOT NO. 31 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No	(✓)
Auto. Dishwasher	Yes (✓)	No	( )
Auto. Wash. Machine	Yes (✓)	No	( )
Site Suitable	Yes (✓)	No	( )

Lot Area 20,000 FTL

Character & Porosity of Soil clay - (SL, micaceous)
Percolation Rate .35
Topography 2-5%
Depth to Water Table > 48"
Rock or other impervious formations None found

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3 @ 80' x 3'
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Tim Simmons

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Trenches shallow - soil is sticky when wet.

CERTIFICATE OF COMPLETION BY Wesley Sparks R.S. DATE 7/29/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold