DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: DAVID BARRER
ADDRESS: 118 ROCKWELL LP
PROPOSED FACILITY: SFR ADD PROPOSED DESIGN FLOW (.1949): 360
LOCATION OF SITE: 118 ROCKWELL LOOP
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut

APPLICATION DATE ___
DATE EVALUATED: 5-30
PROPERTY SIZE: ~.5AC
PROPERTY RECORDED: YES
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	3% LINEAR	0-23	C,M,SBK	SSSPSEXPFR	—	49"	—	—	.35
		23-34	CL,M,SBK	SSSPSEXPFR	—				
		34-49	CL,M,SBK	SSSPSEXPVFR	—				
2	3% LINEAR	0-24	C,M,SBK	SSSPSEXPFR	—	48"	—	—	.3
		24-48	CL,M,SBK	SSSPSEXPFR	—				
3	3% LINEAR	0-48	CL,M,SBK	SSSPSEXPFR	—	48"	—	—	.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	5	5
System Type(s)	GRAVEL	GRAVEL
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: [signature] REHS
OTHER(S) PRESENT: ___

COMMENTS: ___