IREDELL COUNTY HEALTH DEPARTMENT PWH# 4654-77-4804

13076 (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ray Mozeley DATE 9/6/91 PERMIT NO. IC-7-A-4

PHONE: Business _____ Home 399-0695

LOCATION Davidson Downs - Presbyterian Rd.; 115 S TL Presbyterian TR 1st Davidson Downs entrance, to 2nd lot on (L) S. R. No. _____

SUBDIVISION NAME Davidson Downs LOT NO. 49 SECTION OR BLOCK NO. 2

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 4 No. Bathrooms 2 1/2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil p - clay - s - sf
Percolation Rate 35 4/70
Topography _____
Depth to Water Table >48"
Rock or other impervious formations none observed

Lot Area 100' X 225'

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 6 @ 76' X 3'
Sq. Ft. 1371 Linear Ft. 457
Depth of Stone in Lines 12"
Water Supply: Individual (✓) comm. well
Public ( )

Installed by Richard Abernathy

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Soils s.f, and sticky when wetted.

CERTIFICATE OF COMPLETION BY Wesley Sparks R.S. DATE 9/6/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold