4654859126

IREDELL COUNTY HEALTH DEPARTMENT

08309

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Johnny Broome Jr. DATE Jan 4 '89 ~~PERMIT~~ Quad NO. 21-D

PHONE: Business _____ Home _____

LOCATION 115 S. TL 1138 (Presbyterian Rd.) TR Sink Farm Road to end Bear Rt 1/8 mile on Rt. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1-2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Character & Porosity of Soil Clay

Percolation Rate ~.35


Topography 4-6%

Depth to Water Table 4'+

Rock or other impervious formations none obs.

Lot Area 2AC

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2

Sq. Ft. 690 Linear Ft. 230

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Well at old house

Installed by Wayne & Johnny Broome

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DPH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE 1-4-89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

08309

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Johnny Broome Jr. DATE Oct 27, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115 S. to 1138 (Presbyterian Rd.) to R Sink Farm Rd. at end Bear Rt (go thru Red Gate) ¼ mi on Rt. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 1-2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site-Suitable PS Yes ( ) No ( )
Lot Area 2 AC

Character & Porosity of Soil clay
Percolation Rate ~35
Topography 4-6%
Depth to Water Table 4'
Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 690 Linear Ft. 230
Depth of Stone in Lines 12"

Water Supply: Individual (✓) EXISTING
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Johnny V. Broome Jr.

IMPROVEMENTS PERMIT BY Wade R. Hamm Jr. RS.

COMMENTS: follow contour with drayfield. Install trenches at a depth of 30" MAX. to bottom of ditch

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold