IREDELL COUNTY HEALTH DEPARTMENT 4654-89-7158

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Von Stronach DATE Feb 24 '87 PERMIT NO. 77

PHONE: Business _____ Home _____

LOCATION 115 S. TR 1138 (Presbyterian Rd.) ~¼ mile past Cardson Downes TR at end on Rt. S. R. No. _____

SUBDIVISION NAME Gail's Land LOT NO. 7 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2


Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Lot Area 3.8 Ac

Character & Porosity of Soil Clay
Percolation Rate 2.4 area of drainfield
Topography 10-15%
Depth to Water Table 3+
Rock or other impervious formations none obs.

1000 gal P.T

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement



Plot of System

TO SR 1138 →

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. _____ Linear Ft. 150'ea
Depth of Stone in Lines 16" T&J panels
Water Supply: Individual (✓)
Public ( )

Installed by Wilfred Bridges

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY D R Hinson, R.S. DATE Feb 24 '87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold