EPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ___ OF ___
PROPERTY I.D.#: 110602
PROPERTY RECORDED: ___
COUNTY: IREDELL

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: STACY HILL OWNER: AGENT: PHONE:
ADDRESS: 160 MT MOURNE LP. APPLICATION DATE: DATE EVALUATED: 1/3/03
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: 1155 TR LANGTREE TL MTMOURNE LP. ON (L) after curve
WATER SUPPLY: On-Site Well ✓ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	~cc 1-2%	0-5	GR / 0 LAYER l	1:1 / FR SS-NP	FAINT CH 3 "	PS	PS		.3
		6-26	wk SBK / hcl R-YR	1:1 / FI SS SP					
		27-39	SBK / c YR	1:1 / VFI S SP					
		40-48	wk SBK / c YR	1:1 / VFI SS-P.					
2	~cc 1-2%	0-7	GR / 0-l	1:1 / FR SS-SP	FAINT CH 3	PS	PS		.3
		8-39	SBK / hcl R-YR	1:1 / FI S-SP					
		40-49	wk / c YR	1:1 / VFI S-SP					
3									
4									
5									

AVAILABLE SPACE (.1945) PS SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: MAX. .3
EVALUATED BY: Spanks OTHER(S) PRESENT: SAM HILL
COMMENTS: OLD WELL MUST BE PROPERLY ABANDONED