4655153794

13136

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Daniel Sandahl DATE Oct. 22, '91 PERMIT NO. 2H-19-A-5

PHONE: Business _____ Home _____

LOCATION 115 S. TL across from 1102 (Langtree Rd.) on left near end S. R. No. _____

SUBDIVISION NAME Torrence Tavern Estates LOT NO. 5 SECTION OR BLOCK NO. BIK B

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

~~Site Suitable~~ PS Yes (✓) No ( )

Lot Area ~1 Ac

Character & Porosity of Soil PS clay


Percolation Rate ~35

Topography ~ 4%

Depth to Water Table 4'+

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 1080 Linear Ft. 360

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Delbert Bolton

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH D box w/ speed levelers

COMMENTS: _____

CERTIFICATE OF COMPLETION BY DRHinson, RS. DATE 10-22-91

SEWAGE SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold