12849

# IREDELL COUNTY HEALTH DEPARTMENT

P/WH 4655-18-8693

## IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR William H. Dobson / Stephen Turley DATE Jan. 31, 192 PERMIT NO. 248-A-116

PHONE: Business _____ Home _____

LOCATION 115 S. TL 1136 TL 1st Fremont Loop on left

S.R. No. _____

SUBDIVISION NAME Fremont Park LOT NO. 118 SECTION OR BLOCK NO. 2

House ☑ Mobile Home ☐ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 20,800 ft² +

Soil Characteristics ps clay


Application Rate ~.3

Topography ~6%

Depth to Water Table 41

Rock or other impervious formations None obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement ✓ Crawl Space




Plot of System (Not to Scale)

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. _____ Linear Ft. 210 ft

Depth of Stone in Lines 16" gravel

Water Supply: Individual ☐ Public ☑ CW block

Installed by J.R. Bowles

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY W.S.

COMMENTS Driveway must be installed to avoid septic system. Install water line 10'+ from septic system.

CERTIFICATE OF COMPLETION BY Wesley Sparks, RS & Jack R. Hinson, R.S. DATE 1-31-92

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold