Midway
211
20' C.M.
80.0'
100.0'
10'
N61°25.8'E
25.8'
N26°45.2'W
100.0'
S68°55'E 220.0'
N68°55'W 220.0'
1
2
1
2
N27°15'E 100.0'
149.1'
100.0'
10'
CONCRETE MONUMENT
BEGINNING CORNER
IRON
C. M. DAVIS
B. 240 P. 18

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ *of* ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Freemont Pk. 2 PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 4%	0-9	scl sbk	fr ss sp					PS 0.4
		9-48	SL sgp	fr ss sp					
2		0-11	scl sbk	fr ss sp					PS 0.4
		11-48	sl sgp	fr ss sp					
3		0-11	c sbk	fr ss sp					PS 0.35
		11-29	cl sbk	fr ss sp					
4		0-4	sl sbk	fr ss sp					PS 0.4
		4-14	cl ind sgp sbk	fr ss sp					
		14-48	sl sgp	fr ss sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Site LTAR		

OTHER FACTORS (.1946): _____

OTHER(S) PRESENT: _____