IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Otho Cass DATE 8-7-75 PERMIT NO. 180

PHONE: Business _____ Home _____

LOCATION US 70 to 115 36 ½ mi TL on Pond Rd

S. R. No. _____


SUBDIVISION NAME Fremont Park LOT NO. 136 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes (✓)	No ( )	Character & Porosity of Soil	Sandy loam	Porous ✓ Good
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	Within 24 hrs	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2 2b Slope	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	10'	
			Rock or other impervious formations	None	

Lot Area 1 acre



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 18"

Water Supply: Individual ( )
Public (✓)

Installed by E. J. Ervin

IMPROVEMENTS PERMIT BY John Houston

COMMENTS: _____

CERTIFICATE OF COMPLETION BY John Houston DATE 8-27-75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold