)IVISION OF ENVIRONMENTAL HEALTH
)N-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

)WNER: Jimmy Grindstaff APPLICATION DATE _____
.DDRESS: _____ DATE EVALUATED: 2/10/03
'ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
.OCATION OF SITE: 211 Freemont Lp PROPERTY RECORDED: _____
VATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
:VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
'YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	In Repair Drainfield	0-18	Brn SCL	GR FR					PS .3
		18-48"	Rd/Brn C/Cl	m-w SBK SS, SP, SS, FI-FR					
			w/ Few	Yellow brown mottles					
2	Below Repair lines	0-26"	Brn SCL/C	w/SBK-massive					U at 26"
		27"	Chroma 2	Glade					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

:OMMENTS: _____