IREDELL COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Don Carney

DATE REQUESTED: 8-25-80

ADDRESS:

PLAT NO.:

COUNTY: Iredell

LOT SIZE: 100' x 175'

LOCATION OF SITE: Lot 11, Freemont Park 1155. TL 1136
TL 1st entrance Freemont Park at bend in curve

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U 6-8%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) U Clayey	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) U tight p.m.	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S (PS) U 36"	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	S (PS) U 36"+	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S (PS) U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) U 120 mpi	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	P.S.			
SOIL SERIES	Ceil p.m.			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments:

Described By: DRH

Title: SI

Date: Aug. 25, 1980

DHS Form 2601 (2/77)
Sanitation