DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

OWNER: Art Channel APPLICATION DATE ___
ADDRESS: ___ DATE EVALUATED: 7/14/05
PROPOSED FACILITY: MOD. PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: ___
LOCATION OF SITE: 282 Sapphire Inn PROPERTY RECORDED: ___
WATER SUPPLY: [X] Private [ ] Public [ ] Well [ ] Spring [ ] Other ___
EVALUATION METHOD: [X] Auger Boring [ ] Pit [ ] Cut
TYPE OF WASTEWATER: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	CC IR Terrace Below	0-15	lfsbk scl	fr					
		15-24	sbk scl	fr					
		24-31	2fsbk cl	fr					
		32-38	m c	fi p+se x p	CH 3 4R present				
		38+							
2	CCL Terrace Meadow	0-12	scl sbk	FR ss-sp	PS / B				
		13-18	cl m sbk	FR ss-sp	1 4R				
		19-32	mic cl m sbk	FR ss-sp	PS / R				
		33-48	mic sl mf sbk	VFR ss-NP.	PS / 4R				
3	upper terrace	0-25	scl mmsbk	FR-ss-sp	PS / R				
		26-48	sl mf sbk	FR ss-NP (SAMPLE incl.)	S / R				
4									

Soil Notes
Approved

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	G-25%	G-25%
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

COMMENTS: ___