10928

PIN# 4655-60-9015

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Robert M. Cox Sr. DATE Feb. 9, 1990 PERMIT NO. 1C-9-A-5

PHONE: Business 663-0156 Home 664-7960

LOCATION 1155 TL 1137 (Midway Lake Rd.) ~ 1mi TR Beracah Place ~ 500' on right S. R. No.

SUBDIVISION NAME Beracah Place LOT NO. 5 SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other (+ Extra kitchen)


No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area 2 ac

Character & Porosity of Soil ps clay
Percolation Rate ~.4
Topography 4-6%
Depth to Water Table 4' +
Rock or other impervious formations none obs.

~30'

_____ Basement with Plumbing _____ Basement without Plumbing ___✓___ No Basement



Plot of System

Size of Tank 1500 Gals.

Nitrification Field:
No. of Lines 4@100'
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

10' ↔ Lot Line

Installed by Wayne Dobison

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Sam Ingram EHS DATE Feb 9 1990

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold