DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Ronnie Fearing APPLICATION DATE _____
ADDRESS: Tonya Lane DATE EVALUATED: 1/17/03
PROPOSED FACILITY: 3BD. PROPOSED DESIGN FLOW (.1949): 360GPD. PROPERTY SIZE: _____
LOCATION OF SITE: first vacant lot on L, past Pat Lucas PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LAND-SCAPE POSITION/ SLOPE % | HORI-ZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 2% ~CCL | 0-13 | sbk / l | FR SS SP | | | | | .35 |
| | | 14-26 | MSBK / cl | FI S SP | | | | | .25 |
| | | 27-35 | MF sbk / sicl | FR SS SP | | | | | .3 |
| | | 36-49 | MM SBK / cl | VFR SS SP | | | | | .3 |
| | | | | | | | | | |
| 2 | Complex " | 0-11 | sbk / l | VFR SS SP | | | | | |
| | " | 12-29 | MM SBK / cl | FI SS SP | | | | | .3 |
| | | 30-48 | MF sbk / scl | FR SS SP. | | | | | .3 |
| | | | | | | | | | |
| | | | | | | | | | |
| 3 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____