DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET 1 OF 1
PROPERTY I.D.#: 2326
PROPERTY RECORDED:
COUNTY: IREDELL

# SOIL/SITE EVALUATION
## FOR
## ON-SITE WASTEWATER SYSTEM

APPLICANT: BILL MILLER OWNER: ✓ AGENT: PHONE: 663-4309
ADDRESS: Rt 11 Box 115 APPLICATION DATE: 4/3/93 DATE EVALUATED: 5/27/93
MOORESVILLE PROPOSED FACILITY: 2 - 2 BEDROOM M.H.
PROPERTY SIZE: 150' X 260'
LOCATION OF SITE: ALMOND RD / 1155 TL MACKWOOR TR ALMOND 4 + 5 JACKSON (R)
WATER SUPPLY: On-Site Well ✓ Comm. Well Public Other EVAL. METHOD: Auger Boring ✓ Pit Cut

| PROFILE # | .1940 LANDSCP POS. (%) | HORIZON DEPTH (IN.) | .1941 STRUCTURE/TEXTURE | .1941 MINERALOGY/ CONSISTENCE | .1942 WETNESS COND. | .1944 RESTRICT HORIZONS | .1948 CLASS OF HORIZ | 1943/ 1956 SAPRLT CLASS. | HORIZON LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 1% | 0-8 | cl | | SF | No | P | P | .125-.3 |
| | | 9-26 | c | | | | | | |
| | | 27-42 | scl | 1:1 | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 2 | 3% | 0-11 | cl | | SF | SP | P | P | .25 |
| | | 12-30 | c | | | | | | |
| | | 31-48 | scl | 1:1 | SF | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 3 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 5 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

AVAILABLE SPACE (.1945) P SITE CLASSIFICATION (.1948): SITE LONG-TERM ACCEPTANCE RATE: .25 - (.3)
EVALUATED BY: Sparks OTHER(S) PRESENT: Bill Miller
COMMENTS: D/W at rear of property ~ 30' from P/L