IREDELL COUNTY HEALTH DEPARTMENT 4656586520

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Kent Chamberlain DATE June 23, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Lawrence Ave. Turn on Norman Drive Bear Rt. on Club Dr. at end on Rt. S. R. No. _____

SUBDIVISION NAME Wilton Forest LOT NO. 8 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other Repair


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable/S	Yes (✓)	No ( )	

Lot Area ~20000sq ft

Character & Porosity of Soil clay
Percolation Rate .3-.4
Topography 6-8%
Depth to Water Table 4'+
Rock or other impervious formations some scattered rock

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 375 Linear Ft. 125
Depth of Stone in Lines 12"
Water Supply: Individual ( )
Public (✓)

Installed by T J Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRL

COMMENTS: _____

CERTIFICATE OF COMPLETION BY D R Ervin, RS. DATE June 23, '88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Robert Kent Chamberlain DATE Feb 24, '87 PERMIT NO. 74

PHONE: Business _____ Home _____

LOCATION Lawrence Ave to Norman Deese Bear Rt on Club Dr. at end on Rt S. R. No. _____


SUBDIVISION NAME Wilton Forest LOT NO. 8 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes (✓)	No ( )	Character & Porosity of Soil	clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	.3-.4
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-4%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4ft
Lot Area ~20000 sq ft			Rock or other impervious formations	none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. _____ Linear Ft. 145'6"
Depth of Stone in Lines 16" Trench panels

Water Supply: Individual ( )
Public (✓)

Installed by J J Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY JRH

COMMENTS: Lowest ditch 5' short because of close distance to underground power line.

CERTIFICATE OF COMPLETION BY J R Hamm, R.S. DATE Feb 24, 87

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold