DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ___ OF ___
PROPERTY I.D.#: ___
PROPERTY RECORDED: ___
COUNTY: ___

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Ron Beuller/Andrea Johnson OWNER: ___ AGENT: ___ PHONE: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: ___
PROPOSED FACILITY: ___
PROPERTY SIZE: ___
LOCATION OF SITE: lot 18, Club Dr. (Wilton Forest)
WATER SUPPLY: On-Site Well ___ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Borings

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	.1943/ 1956 SAPRLT CLASS	HORIZON LTR
1	LS ~10%	0-6"	gr - scl	1:1 fr			PS		• 6
		6-20"	wk SBK - c	1:1 fi			PS		• 4
		20"+	wk SBK - sicl w/ rock	1:1 s sticky, s plas			U	—	
2		0-6"	gr - scl	1:1 fr			PS		• 6
		6-28"	SBK - c	1:1 fi			PS		• 4
		28-41	wk SBK - sic	1:1 fi			PS		• 3
		41+	wk SBK - sicl (SAP)	1:1 vfi			U		—
3									
4									
5									

AVAILABLE SPACE (.1941): U SITE CLASSIFICATION (.1948): U SITE LONG-TERM ACCEPTANCE RATE: ≤ 3
EVALUATED BY: DRJohnson, PS OTHER(S) PRESENT: ___
COMMENTS: Site can be reclassified PS per rule = 1956 PPBPS, modified system