4657217505

IREDELL COUNTY HEALTH DEPARTMENT

1538

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Denise B. Armstrong DATE Oct-17,'90 PERMIT NO. part of 2 IKA15

PHONE: Business _____ Home _____

LOCATION 150 W. 72 21 S. on Right past 2nd Dry Dock Loop and before Denver Distributing S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


Modular

House ( ) ~~Mobile~~ Home (✓) Business ( ) Other _____

No. Bedrooms 3	No. Bathrooms 1½		Character & Porosity of Soil	Psclay	
Garbage Disposal Unit	Yes ( )	No (✓)	Percolation Rate	2-4	
Auto. Dishwasher	Yes (✓)	No ( )	Topography	2%	
Auto. Wash. Machine	Yes (✓)	No ( )	Depth to Water Table	6ft	
Site ~~Suitable~~ PS	Yes (✓)	No ( )	Rock or other impervious formations	none obs.	

Lot Area 60000 ft2+

_____ Basement with Plumbing _____ Basement without Plumbing ___✓___ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 90 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Wayne Potts

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: well not installed. Drainfield slightly deeper than anticipated (+36" trench bottom) but no problem seen with soil.

CERTIFICATE OF COMPLETION BY David R. Hinson, REHS DATE 10-17-90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold