4657324541

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Joseph James DATE 6-14-85 PERMIT NO. 169

PHONE: Business / Home

LOCATION Hwy 21, on left Across from Dry Dock Loop
TR Vadalia Drive 2nd house on left S. R. No.

SUBDIVISION NAME LOT NO. SECTION OR BLOCK NO.

House ( ) Mobile Home ( ) Business ( ) Other REPAIR

No. Bedrooms 3 No. Bathrooms 1

| | | | | |
|---|---|---|---|---|
| Garbage Disposal Unit | Yes ( ) | No (X) | Character & Porosity of Soil | |
| Auto. Dishwasher | Yes (X) | No ( ) | Percolation Rate | |
| Auto. Wash. Machine | Yes (X) | No ( ) | Topography | Existing |
| Site Suitable | Yes ( ) | No ( ) | Depth to Water Table | System |
| | | | Rock or other impervious formations | |

Lot Area EXISTING


___ Basement with Plumbing ___ Basement without Plumbing X No Basement

WASHER 60X

Size of Tank 75 Gals.

Nitrification Field:
No. of Lines 1
Sq. Ft. 240 Linear Ft. 50
Depth of Stone in Lines 12

Water Supply: Individual (X)
Public ( )




Plot of System

Installed by F. J. Erwin Co.

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

IMPROVEMENTS PERMIT BY F. H. C.

COMMENTS:

CERTIFICATE OF COMPLETION BY Fred Clement DATE 6-14-85

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

11:00

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Joseph James DATE 4-25-85 PERMIT NO. 135

PHONE: Business _____ Home _____

LOCATION Hwy 21S on left 2 miles from Troy Lock Loop Tr Vadalia Drive 2nd house on left S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (X) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1

| | | | | | |
|---|---|---|---|---|---|
| Garbage Disposal Unit | Yes ( ) | No (X) | Character & Porosity of Soil | | |
| Auto. Dishwasher | Yes (X) | No ( ) | Percolation Rate | | |
| Auto. Wash. Machine | Yes (X) | No ( ) | Topography | EXISTING | |
| Site Suitable | Yes (X) | No ( ) | Depth to Water Table | | |
| | | | Rock or other impervious formations | | |

Lot Area _____

_____ Basement with Plumbing _____ Basement without Plumbing X No Basement




Plot of System

Size of Tank 75 Gals. WASHER 60X

Nitrification Field:

No. of Lines 1

Sq. Ft. 240 Linear Ft. 80

Depth of Stone in Lines 12"

Water Supply: Individual ( )

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: X Joseph L James

IMPROVEMENTS PERMIT BY Fred Clemmer

COMMENTS: Separate Washer from Rest of System

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold