DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: J. Douglas Turner
ADDRESS: _____ APPLICANT: _____
PROPOSED FACILITY: _____ APPLICATION DATE: _____ DATE EVALUATED: 11/5/04
LOCATION OF SITE: Charlotte Hwy PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Alt 1	0-10"	Brw SCL	GR, FR					
		10"-48"	Rd/Brw C/C	m-w SBK SS, SP, SE, FI-FR w/ common Mica Flakes & few to many SAP Indus					PS .3
2	Alt 2	0-10"	Rd/Brw C	w SBK SS, SP, SE, FR w/ Common Mica Flakes					PS .25 to .3
		10-24"	Brw to Rd/Brw SCL	GR, FR Some Mica					
		24"-48"	Rd to Rd/Brw	FR-FR w-m SBK SS, SP, SE + Yellow/brw mottles starting @ 37" Wetness in hole at 42"					
3									
4	Front Yard (Repair)	0-10"	Brw SCL	GR FR					
		10-24"	Yel/Brw C/C						
		24-48"	Rd/Brw C/C	m-w SBK SS, SP, SE, FR w/ Common Mica Flakes & Few Yel/Brw mottles @ 40"					PS .3

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____