Type III

1667

IREDELL COUNTY HEALTH DEPARTMENT 465738 4497

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Tony Wagoner (Countryside Development) DATE 8/27/91 PERMIT NO. 1LA 59

PHONE: Business 664-6989 Home

LOCATION 21N from 150W, on ® just past Brentley Acres Rd intersection

S. R. No. 21N

SUBDIVISION NAME LOT NO. SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil P - cl - sicl (sf)
Percolation Rate .35 - .4
Topography 2% - 3%
Depth to Water Table > 48"
Rock or other impervious formations None found

Lot Area .62 AC

___ Basement with Plumbing ___ Basement without Plumbing ✓ No Basement




Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3@67'
Sq. Ft. ___ Linear Ft. 200 *
Depth of Stone in Lines
Water Supply: Individual ( )
Public ( )
* 16" Prefabricated Porous Panel System
Installed by FT Erwin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

IMPROVEMENTS PERMIT BY

COMMENTS:

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 8/27/91

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold