WASTEWATER SECTION

PROPERTY ID: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Randal Sprinkle APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7/10/
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: _____ PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-38"	Rd/Rd-Brn CL	m-F SBK SS, SP, SE	Fi-Fr Few to many SAP in clus				.3 to 38" PS
		38-48"	CL SAP		w/ low Chroma mottles				
2		0-8"	SCL	GR					.3 to 36" PS
		8"-36"	R/Rd-Brn Clay	F SBK SS, SP SE	FR w/ Few to many SAP in clus				
		36"-48"	Yel-Brn SAP		w/ Chroma 2 mottles				
3		0-14"	Brn SCL	GR					.3 PS
		14"-40"	Rd-Rd Brn CL	m-F SBK SS, SP, SE	FR w/ many common Mica flake				
			w/ SAP in clus						
		40"-48"	Rd/Brn CL	SAP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____