...RTMENT OF ENVIRONMENT AND NATURAL RESOURCES
...VISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

OWNER: Christine Allen APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 9/25/02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Red Dog (Horse Barn) PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	AH	0-10"	Brw SCL GR FR						PS .3
		10"-36"	Rd/Brw C/CL w/m-w SBK SS, SP, SE, FI- FR w/Few to many SAP Inclus						
		36"-48"	L SAP w/ Inclus of C/CL & some w. Rock						
2	AH	0-18"	Brw to Yel/Brw L/ SCL GR FR						
		18"-36"	Brw C/CL w/Few to many SAP Inclus SS, SP, SE, FI-FR						
		36"-48"	C/CL w/ Some light yel/brw mottles & Some SAP Inclus.						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

AH-1

0-10" Brn SCL GR FR

10"-35" Rd/Brn C/Cl w/ m-w SBK SS, SP, SE, F-FR w/ few to many SAP Inclus

36-48" L SAP w/ Inclus of CL & some w Rock

AH2
PS
.25

0-18" Brn to yel/Brn L/SCL GR FR

18"-36" Brn C/Cl w/ few to many SAP Inclus

36"-48" C/Cl w/ some light yel/brn mottles & some SAP Inclus