DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of
PROPERTY ID #:
COUNTY:

# SOIL/SITE EVALUATION
## for ON-SITE WASTEWATER SYSTEM

OWNER: Bubbler Martha Landis
ADDRESS:
APPLICANT:
APPLICATION DATE:
DATE EVALUATED: 4/6/08
PROPOSED FACILITY:
PROPOSED DESIGN FLOW (.1949):
PROPERTY SIZE:
LOCATION OF SITE: Red Doa
PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-12" | Rd/Brn SCL | w/SBK | SP,SE, Inadus | few-to-many | SAP | | PS .3 |
| | | 12-30" | Brn L | FR,SS | | | | | |
| | | 30-48" | Brn SL/L | SAP | | | | | |
| 2 | | 0-10 | Rd/Brn SCL | w/SBK | SS, SP, SE, yellow w/brn | FR w/ Inadus | | | PS .3 |
| | | 10-48" | Rd/Brn C/Cl | m-w/SBK few | | | | | |
| 3 | Repair | 0-10" | Rd/Brn C/Cl | | SS,SP,SE, FR w/SBK | few | common | Mica | .3 |
| | | 10-30" | Rd/Brn C/Cl | & many | | | | | |
| | | 30-48" | L/SL | SAP | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT: