DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Martha Landis APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 10-15-03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Kelthie Acres Lot 25 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1 Initial		0-12"	DL Brn	SCr, GR FR	WSBK SS, SP SE, FR SAP Inclus				PS .3 to 34"
		12"-34"	Brn to Rd/Brn CL						
			lm/few	to many					
		34-48"	SL	SAP					
2 Repair		0-4"	DK Brn SCL	GR FR					PS
		4-20"	Rd/Brn C	mSBK SS, SP SE, FR					Common .3
		20"-48"	Rd/Brn CL	wSBK SS, SP SE, FR w/ Mica Flakes & few to many SAP Inclus					
3			* Note: Previous Soil Evaluation showed R shallow soils				1988. in back of lot		
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____