DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kam APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-12-9
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 23 Oakbrook PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 4-6%	0-14	SaLo r cl	fr ss sp sp					
		14-32	wk sbk mxst brn r cl sapo fr ss sp sp						
		32-55+	wk sbk brn L sap fr wk ss sp						
			Mottled Lite mn 10 sap 32"+						
2	L 4-6%	0-10	SaLo r cl	fr so ss po					C 3 @ 30"
		10-20	mk sbk R brn, g brn c f fr ss sp sap						
		30-50	wk sbk g brn cl ss sap						
3	L	0-15	SaLo r cl	fr so ss po					C 3 @ 30"
		15-33	m sbk R brn, g brn cl fr ss sp sap						
		33-60+	wk sbk brn/g, L sa fr ss sp						
			Sap. appears mottled 72"						
4	L 6%	0-22	SaLo r cl	fr so ss po					
		22-34+	gr SL/L sap	vfr vss p					
			Lite						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____