DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kramer APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 9-26-96
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Lot 98 Cedarcrest PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut now part of Lot 68
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	(1940) LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) (1941) STRUCTURE/ TEXTURE	(1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS (1942) SOIL WETNESS/ COLOR	(1943) SOIL DEPTH	(1956) SAPRO CLASS	(1944) RESTR HORIZ	PROFILE CLASS & LTAR
1	L 6-10%	0-8	gr brwsl	fr					R 634
		8-55+	wk sab r sbl	fi sap Sxp					
			few b.t.s w/ d.						
2	L 6-10%	0-11	sab r sbl	fr sspl sap					
		11-25	gr - g brwsl	fr					
		25-36	wk sab - mass	r brn - g brn sed fi					
		36-51+	massive gl sed clay						
			few m inf tubes						
3	L 6-10% slight variation in depth to bedrock	0-10	gr brwsl	fr	(1944)	(1944)		(1944)	(1944)
		10-36+	BK - mass gl brnsl/sd	fr sl pl sl sti					
			+ chs & drainage features						
			@ 17" slight 24"+						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kwon APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9-20-24
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 19 Pelham PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut now part of Lot 68
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 4-6%	0-8	gr-sab pbk sc l-fr						PS .3
		8-28	m sab pbk sc l	fr ss sp sp					
			w/ mod sap						
			few manganese w.						
2	L 4-6%	0-6	gr bro. m blend sc l fr						PS .25 @ 33"
		6-15	sab. m c/c l fr soft						
		15-33	m sab y brn/c/c w numerous distinct ft sp sap/mod?						
		33-50	massive y-brn mod mottles sc l sap numerous bitumen						
		50-55+	massive g c l sap numerous bitumen wet						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

NEED WORK SOIL - JMO (W Pkc)
@ Street
9-20-24