DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kinser APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9-20-2
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 69 Oakbrook PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

New part of Lot 69

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1950 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 4 6%	0-6	gr brn sl/sc	L fr					PS ≤3
		6-36	sab R cl/sc	fri/sl bri/sl fr ss sp/sp	mica common				
		36-60+	gr-massive sl/L	n brn sap					
			numerous bits W.R						
			mica common						
2	V 4 6%	0-17	sab R cl	mod fr ss sp/sp	mica common				PS ≤3
		17-28	gr-sab red/brn sc/L	sap	mica common	L ss sp/sp	non-sap		
		28-50+	gr-sab brn L/sl bm	fr ss-ns, np/np			PS		
			mica common many bits W.R.						
3	V 4 6%	0-12	gr brn sl	fr					PS ≤3
		12-36	gr-sab r brn	sl fr ss sp/sp					
		36-48	sab R cl/c	fr sp/sp					
			few bits W.R.						
4	L 4 6% slope?	0-7	gr brn sl/sl						PS ≤3
		7-36	gr-sab red	w/ muscovite common, sl/sp/sp					
		36-48	w-sab L brn	sap					
			mica common, numerous bits W.R.						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Knox APPLICANT: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 9-20-96
PROPOSED FACILITY: ____ PROPOSED DESIGN FLOW (.1949): ____ PROPERTY SIZE: ____
LOCATION OF SITE: Lot 81 PROPERTY RECORDED: ____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

now part of Lot 69

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ	PROFILE CLASS & LTAR
1	L 4-6%	0-16	ap/sub b/w scl fr						B .3 @ 46"
		16-46	sub b c/cl fr	ss sp stp	few brits	wk			
		46-50+	wk sub mass	fgr					
			mm/cm conc brits/w						
2	L 4-6%	0-7	ap/sub b/w scl						B .3
		7-17	sub b cl	fr ss sp stp	few brits/mn				
		17-60+	wk sub mass	rcl fi ss sp stp					
			w/mm conc brits	w. r. pack stp					
3	L 4-6% 9-25-96	0-11	ap/sub b/w sl/scl fr						B .3
		11-48	mk sub b c/cl fi	ss sp stp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): ____
EVALUATED BY: ____
OTHER(S) PRESENT: ____

9-20-96 Need BH#3 AH in front
Look @ moving house back & pumping to front