DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Lawson APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7-2-96
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 101/102 Oakbrook PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Now Lot 79

PROFILE #	1940 LANDSCAPE POSITION; SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (.1941): 1941(1) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941): 1941(2) CONSISTENCE/ MINERALOGY	1941(3) WETNESS/ COLOR	OTHER PROFILE FACTORS: 1941(4) SOIL DEPTH	1956 SAPRO. CLASS	1944(h) RESTR. HORIZ.	PROFILE CLASS & LTAR
1 101	L 6-8% S-Mod Eroded	0-10/19	Sdy rcl	fr		(4)	(4)		(4)
		10/19-48+	w/scat yel brn sl cl sap fr-vfr						
2 101	L ~6-8% Mod-Sev Eroded	0-13	Sdy rcl	fr		(4)	(4)		(4)
		13-48+	w/scat mottled R-brn, y-brn cl sap						
3 102	L 2-4%	0-18	sl brn sl fsa	fr		?			maybe ≤.3 @ ≤30"
		18-48	w/scat mott yel cl fr-vfr sap						
			numerous gravel in sl cl sap & bedrock						
4 102	L ~8%	0-10	sl brn sl fcl	fr					.15 .3 @ ≤30"
		10-20/33	Sdy rcl	fi ss/sc/cm					
		20/33-55	w/scat mott y-R, brn R cl sap	fr-vfr					
		LPP	Saprolite - stone and boulder pit w/scat mott cl fr						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

102 ≥5 0-21 Sdy rcl fr SAP
21-46 w/scat mottled yel brn cl sap (4)