DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## for ON-SITE WASTEWATER SYSTEM

OWNER: Freedom Homes/Daryl Holiday APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 3/28/03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: 128 Evelyn Ln PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | Behind mtn ~15' | 0-10" | Brw SCL | GR FR | | | | | |
| | | 10"-36" | Rd/Brw C/CL | m-w SBK | SS, SP, SE, FR | | | | PS .3+ |
| | | | w/ Few to many | SAP | P Inclus | | | | |
| | | 36"-48" | Yel/Brw L | SAP | w/ Few CL Inclus | | | | |
| 2 | ~20' off Back PL | 0-8 | Brw SCL | GR FR | | | | | |
| | | 8-32 | Rd/Brw C/CL | m-w SBK | SS, SP, SE, FR | | | | w/Few PS .3 |
| | | | to many | SAP | P Inclus | | | | |
| | | 32"-48" | Yel/Brw L | SAP | w/ Few CL Inclus | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____