DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
ENVIRONMENTAL HEALTH
WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kerr APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 9-10-92
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 99 Oak Brook PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

KEEP LATERALS SHALLOW
now part of Lot 78 (drainfield area)

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 4%	0-19	SBk R CL	Fr SS SP SE			PS		1.3
		19-26	m-w SBk R CL/sapric	Fr SS SP					
		26-60	w SBk L/sap	Fr SS SE/NP					
				Bits of weathered rock					
				few CL inclusions					
2	L 4-6%	0-17	ms SAL R c/cl	fr SP SE/P			(4)		
		17-32	wk SAL w R c/sapric	fr SS SP/PS/NP					
		32-60	wk SAL-mucky sapric L/sap						
3	L 4-6%	0-17	SAL R c/cl	fr SP SE/P		4-6 PS			1.5
		17-31	wk SAL R c/L w/sapric	fr-fr SS SP/sap					
		31-50	wk SAL cl/sap						
		50-64+	SL/L/sap-fpe						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
System LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

...MENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
...OF ENVIRONMENTAL HEALTH
...WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Known APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 7-12-96
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Lot 100 Oak Brook PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed 3 bin Trench
Now part of Lot 78 House/well area

PROFILE	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	L 1	0-19	msBk R CL	Tans weathered rock mica's Fr	mica's Fr SS SP SSP				PS .3+
		19-30	wSBk RCL incl	sap mic Fr	SS SP				
		30-60	SL sap	Fr SS NS NP					
				P					
2	2 Var. Depth L=25%	0-12	SBk R CL	mic Bit weathered Rock Fr	SS SP SSP				PS -3
		12-30	wSBk YR L incl	sap Fr SS SP					
		30-60	SL sap	Fr					
3	L Alpine	0-17	SBk RC/CL						
		17-60	wSBk CL sap/ mmmc	L SSP SLP			4		
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___