DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Known APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 7-18-96
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Lot 97 Oak Bank PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

now part of lot 96

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	1 Linear	0-10	gr lgr sol						PS .3 @ ≤ 36"
		10-36	mwksbk R c/pCL	Fr sp					
		36-55	wk sbk-massive R sel fi-vfi						
			w/ few bits wx						
			remnants of bedrock						
2	2	0-7	gr Br SL/CL			24 max trench bottom			PS .3 @ ≤ 36"
		7-24	mssbkRV CL	Fr SS SP SEXP					
		24-60	wsbk YBr CL	few redmottles Fr VFi few bits wx few incln sap					
3	3	0-7	gr Br SL/SCL						PS .3 @ ≤ 31"
		7-31	msbk R/MR CL	Fr SS SP					
		31-44*	wsbk massive R/MR	SCL/CL Fi SSSP Numerous YBr mottles few < 2 chroma roots					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Usable Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___