DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Bill Ball APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-6-96
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 3 bdrm PROPERTY SIZE: _____
LOCATION OF SITE: Lot 2 Farmdale PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	10-15' debris drainage toeslope 6-8%	0-8	gr brn scl	fr					
		8-36	sbk y-R C	fi, so					
		38-48	sbk R CL	fr, ss, so					
			few f/K manganese stains						
2	L 8-10%	0-5	gr brn scl	fr					
		5-48	sbk R	fr, ss, so					
			few mottles	12"+					
			some ch 2 @ 26-30"						
3	L 6%	0-9	gr brn sl/scl	fr					
		9-26	sbk RC	fi, so					
		26-48	sbk R CL	fr, ss, so					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____