DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Bill Ball 565-8266 Mark 244-0267

OWNER: Bill Ball APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-7-96
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 360 gpd PROPERTY SIZE: _____
LOCATION OF SITE: Lot 1 Farmdale PROPERTY RECORDED: _____
WATER SUPPLY: ~~Private~~ ☐ Public ~~Well~~ ☐ Spring ☐ Other _____
EVALUATION METHOD: ~~Auger Boring~~ ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ~~Sewage~~ ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 6-8%	0-3	gr - lam sl fr						.3+
		3-14	SAB RC	f sp 1:1					
		14-48	MSAB RCL	fr ss sp 1:1					
			micaceous, few inch sp						
2	L 2/10%	0-10	SAB ybr scl	fr					.3+
		10-16	SAB RC	fi-fr ss sp					
		16-48	SAB RCL	fr ss sp					
			mottles present	to 36"					
			Sand < ch 2 24-36" - not present 36-48" (redox ?)						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____