DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kunz APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-15-98
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 17 Collins Pointe PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-12	SaBr fine sc	fri SO					PS .3 @ 45"
		12-45	wk fine SAB w/ R/P channels	w/ common SAP/ burrows					
		45-48	massive ≤L SAP	fri					
2		0-15	SaBr fine sc	fri SO					PS .3 @ 45"
		15-24	wk SAB red	common [illegible]					
		24-48	L SAP	fri SO SAP					
				roots	little gleying				
3		0-5	gr brn scl						PS .3 @ 45"
		5-22	SAB fine sc	fri SO SAP					
		22-48	wk SAB fine sc w/ fri SO SAP						
			and fine sap	increasing w/ depth					
4		0-5	gr brn scl/scl fr						PS .3+ @ 45"
		5-14	SAB fine sc	fri SO SAP					
		14-28	mod SAP RED	fri SO SAP w/ depth					
		28-48	wk SAB - massive cl/L w/ common mica SAP						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____