ON-SITE WASTEWATER SECTION

COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Known APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-16-94

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: Lot 6 Valley Park II PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1950 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1		0-5	Gr brn sl/scl						PS -34
		5-20	sbk rc	fi sp					
		20-48	sbk	fi sp wo					
		48-60	L sbk	fi sp wo					
			Looks like good capable						
2		0-6	sbk brn scl	fr					PS -34
		6-15	sbk rc	fi sl plas/sl stky					
		15-60	L - sl sbk	fi sl sp wo					
3	15%	0-6	gr-sbk brn scl	fr					PS -15
		6-15	sbk rc	fi-fr sp wo					
		15-26	many fe stain of the below						
		26-60	chro L sbk mott						
4		0-13	gr brn sl scl	fr					PS -15
		13-23	sbk rc scl	fr					
		23-40	gr R scl	fr	4.97				
		40-48	wk sbk rc scl	fr sp wo					
			mottles brn mottles, bri						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____