SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

COUNTY: _____

OWNER: K _____ APPLICANT: _____

ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5/17/95

PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

LOCATION OF SITE: Lot 3 Collins Park II PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

100' well setback from Septic System

PROFILE #	1940 LAND SCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 24%	0-11	sl cb rcl	fr ssp					B .34
		11-24	wk sbk rbrn cl/l	few fi sap	fr ssp sap				
		24-48	l/sl sap	fr ssp-np					
		48-60	sl sap	fr ss np-sp	Great saprolite				
2		0-10	sl cb rc	fr sp					B .37
		10-25	wk sbk rbrn cl/l	fr ssp	fi sap, fr ssp				
		25-48	massive rbrn l/sl sap	fr ss sp-np					
		48-68	sl sap	fr ss sp —	great saprolite				
				looks like good saprolite					
3		0-17	sl cb rc/cl	few fi sap fr ss sp					B .31
		17-48	massive l/sl sap	fr ss sp-np					
		48-60	massive brn l/sl sap	fr ss sp-np	— Good saprolite				
4	L 3%	0-17	sl cb rc	fr sp					B .3
		17-29	mt sbk R, yr cl	fr ss sp sap					
		29-60	mt sbk yr cl/l	common fi sap fr ss sp sap					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____