VISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

APPLICANT: _____ DATE EVALUATED: 9-20-00
WNER: _____ APPLICATION DATE: _____ PROPERTY SIZE: _____
DDRESS: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY RECORDED: _____
ROPOSED FACILITY: _____
OCATION OF SITE: Lot 24 Grove Meadow
/ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-5	gr-sl sd sl						PS .3
		5-21	m-cobbly grc	fr sp					
		21-46	(R-C) wk sbk	ry scl fr ss sp common in bsp					
		46-65	marine	ry L/scl sp fr ss sp					
2		0-6	brw scl	fr ss sp					PS .3
		6-28	Sab RC	fr ss sp					
		28-60	B-C/CB	L common in bsp / L sp					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
vailable Space (.1945)		
stem Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____