DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION



# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Full Spectrum Realty — APPLIC. DATE E
ADDRESS:
PROPOSED FACILITY: — PROPOSED DESIGN FLOW (.1949): — PROPERTY SIZE:
LOCATION OF SITE: Lakeland Dr #177 — PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut — TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | In Initial | 0-5 | Rd/Brw SCL | FR w/SBK | | | | | PS |
| | | 5-20 | Rd/Brw C/CL | m-w SBK | | | | | |
| | | 20-32 | Yel/Brw SL/L | SAP w/Common C Incls & Mg Incls | | | | | .25 to |
| | | 32-48 | Yel/Brn to Rd | SL/L SAP | | | | | .3 |
| | | | | | | | | | |
| 2 | Initial | 0-5 | Brw | SCL w/SBK | w/ Incls of SAP | | | | PS |
| | | 5-24 | m-w SBK CL | | | | | | |
| | | 24-48 | L SAP/CL | Common Mica | | | | | .3 |
| | | | | | | | | | |
| | | | | | | | | | |
| 3 | Behind Hse | 0-3 | Brw SCL | | | | | | PS |
| | | 3-12 | Rd/Brw | | | | | | |
| | | 12-24 | Rd/Brw to | | Yel/Brw CL/C | | SAP | w/Incls of SAP | |
| | | 24-45 | Yel/Rd/Yel/Brw | | | | | | .3 |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT: