SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Pruitt OWNER:__ AGENT:__ PHONE:__
ADDRESS:__ APPLICATION DATE:__ DATE EVALUATED:__
PROPOSED FACILITY:__
PROPERTY SIZE:__
LOCATION OF SITE: Lot 76 Wintwarb Pt.
WATER SUPPLY: On-Site Well___ Comm. Well___ Public___ Other___ EVAL. METHOD: Auger Boring___ Pit___ Cu

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZ LTA.
1	Linear 6 to 8%	0 to 26	C SBK	SEAP SS SP	PS	PS	PS	N/A	.32
		26 to 48+	SCL WSBK	NEAP NS NP					
2	Linear 6 to 7%	0 to 5	L GR		PS	PS	PS	PS	.3
		5 to 26	C SBK	SEAP SS SP					
		26 to 42	SCL WSBK	NEAP WS NP					
		42 to 48+	Clay	Saprolite					
3									
4									
5									

AVAILABLE SPACE (.1945) Yes SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: F. C. Moore OTHER(S) PRESENT:
COMMENTS: about 1/2 of lot has unsuitable Topography