DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Brett Berlo — APPLICANT: _____ — DATE EVALUATED: 6/24/97
ADDRESS: _____ — APPLICATION DATE: _____ — PROPERTY SIZE: _____
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY RECORDED: _____
LOCATION OF SITE: Lot 34 Wendland Pl.
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LL 2-4%	0-18"	Brn, C/L, m, SBK	SS, SPS, E, Fr					
		18"-38"	Rd-Brn, L, m-f, SBK	SS, SPS, E, Fr-Fr		w/ SAP inclusions many common			mica flakes PS .25-.3
		38"-48"	Rd-Brn, C/L, SAP mix	SS, SPS, E, Fr					
2	Tight-Compact	0-8"	Brn, SCL, GR	SS, SPS, E, Fr					.3 PS
		8"-48"	Rd-Brn, C/L, m	SBK, SS, SPS, E, Fr-Fr					
			w/ Few SAP inclus						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____